Field Service Bulletin No. 20

Order No.: DD+DIS280.01E

1 piece UTNGO MA1

ADC Solo
Type 5155/100

Path Speed CR SP1001
Type 5155/200

Rating			When?		
safety relevant	reliability	new function	immediately	next service	as required
	X				X

Please file this document in section 13 of your technical documentation

New Software Patch SOLB1302

What is new?

- Network problems of SOL_1302 (warning 216A7 with “VIPS not ready” and communication with Processing Station) are solved with this patch.
- Patch SOLB1302 supports also the new stepper-motor board with Vitalec RAM.

Order Number:

Patch SOLB1302: CM+9.5155.1050.7